



Manufacturers & Stockist Distributors of:
Commercial & Industrial Safety Floorings,
Entrance Matting Systems & Specialist Mats
& Floorcoverings

JAYMART RUBBER FLOORINGS: CENTRAL

CLEANING & CARE

We detail below a suggested treatment programme recommended by BRITISH NOVA WORKS LTD., Beaumont Road, Banbury, Oxon, OX16 7RB. Telephone 01295 254 030 who will provide additional expert guidance if required. Equally adequate alternative cleaning materials may also be used.

1. Initial Treatment

Jaymart "Central" rubber floor covering should be thoroughly cleaned following installation before the application of floor dressing.

a) **Cleaning**

- i) Mop or lightly scrub, depending on degree of soiling, with "NOVACARE" Floor Maintainer, in ratio of 2-4 cupfuls per gallon of water.
- ii) Pick up loose dirt (mop or wet vacuum), rinse with clean cold water. Wipe and allow to dry.

b) **Dressing**

- i) Once you are satisfied that the floor is completely clean and dry, "NOVA LONG-LIFE" Floor Dressing should be applied thinly and evenly as follows:
- ii) Soak a clean twine mop in "NOVA LONG-LIFE" and wring out the excess. A clean Mop bucket is recommended for this process.
- iii) Apply "NOVA LONG-LIFE" evenly, using a left to right movement. Allow to dry (approx 20-30 minutes)
- iv) Apply a second coat after the first is dry, at right angles to the first.

2. Further Maintenance

a) **Daily**

- i) Brush, sweep or vacuum loose litter and dirt.
- ii) Damp mop when necessary, using "NOVACARE" in ratio of 1-2 cupfuls per gallon of cold water. "NOVACARE" will leave a slight sheen which can be enhanced if desired, by buffing with a bristle brush.

b) **Weekly**

- i) Damp mop throughout with "NOVACARE". Particularly dirty areas can be lightly Scrubbed, allowed to dry, and machine burnished with a bristle brush.

c) **Periodic Maintenance**

- i) According to wear, strip off initial treatment using "NOVA STARBRITE" Emulsion Dressing Remover.
- ii) Dilute 1 part of "NOVA STARBRITE" with 8 parts of water (hot if available)
- iii) Wet floor with this solution, allow chemicals to soften old dressing (approx 5-8 minutes). Scrub with bristle scrubbing brush.
- iv) Pick up loose dirt and polish, rinse the floor thoroughly with clean water, and allow to dry.
- v) Re-apply two coats of "NOVA LONG-LIFE" as described for "Initial Treatment" Earlier.

Cleaning and maintenance can be aided, especially where large areas are involved, by the use of a double cylinder brush cleaning machine e.g. Rotowash, RGK Mirage, Prochem.